

Bogen CORE

Release Note

1.0.5.0

[Added]:

- Add [Buffer] element on Audio Streamer component and PPM Touch component to control / delay the speed of audio streaming.
- Add [DSP Error] status on System Status window ; the DSP chip will auto reset when it's not function.

[Modified]:

- While changing value on [Buffer] element when system is offline, it won't be fixed and can be changed to other value when the system is online.

[Fixed]:

- When [frequency Lv] value on Feedback component is reaching over its default value(20 Hz), it will not function to display the status.